

ਦਫਤਰ: ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ ਬਠਿੰਡਾ
ਤੀਜੀ ਮੰਜਿਲ, ਜ਼ਿਲ੍ਹਾ ਪ੍ਰਬੰਧਕੀ ਕੰਪਲੈਕਸ, ਬਠਿੰਡਾ

ਫੋਨ ਨੰ: 0164-2212878 ਫੈਕਸ ਨੰ: 0164-2213878 ਈ.ਮੇਲ:- xenbtiprovl@gmail.com

ਪੱਤਰ ਨੰ: 5822

ਮਿਤੀ: 9/11/21

ਵੱਲ,


Principal

Sri Guru Hargobind Singh Sen. Sec School,
Phooli road Nathana.

ਵਿਸ਼ਾ:-

ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਬਾਰੇ- Sri Guru Hargobind
Singh Sen. Sec School, Phooli Road Nathana.


ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸੰਬੰਧੀ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ:2, ਭਤੇਮ ਸ਼ਾਖਾ ਬਠਿੰਡਾ
ਦੀ ਸਿਫਾਰਿਸ਼ ਸਹਿਤ ਕੀਤੀ ਗਈ ਰਿਪੋਰਟ ਅਨੁਸਾਰ ਆਪ ਜੀ ਨੂੰ ਸਾਲ 2021-22 ਲਈ ਵਿਸ਼ੇ ਅਧੀਨ ਬਿਲਡਿੰਗ ਦਾ
ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ
ਬਠਿੰਡਾ।

ਮਿਤੀ:

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ:2, ਭਤੇਮ ਸ਼ਾਖਾ ਬਠਿੰਡਾ ਨੂੰ
ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ: 1683 ਮਿਤੀ: 06-10-2021 ਦੇ ਸੰਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ
ਬਠਿੰਡਾ।

PERFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING

1. Name of the School SRI..GURU..HARGOBIND..CONVENT..SEN..SEC:.....
2. Location
.....SCHOOL, NATHANA..151102, POOHLI..ROAD..NATHANA.....
3. Plot Area
.....19..KANAL..16..MARLA.....
4. Plinth Area39.537..SQ..FT.....
5. No. of Stories03.....
6. Year of Construction2013.....
7. Whether the building has been constructed under the supervision of the Qualified Engineer, if so.
 - a) Name of the Engineer with Qualification NAVARAJ..SINGH..GIREWAL.....
 - b) Address BATHINDA.....GOLE..MARKET.....SCO.-9.....
.....2ND..-FLOOR.....
 - c) Set of structural drawing used in Construction
8. Whether the building has been Constructed for the purpose of :-
 - a) School (Yes/No)
 - b) Residential purpose (or) (Yes/No)
 - c) Converted for School (Yes/No)
9. Material used for Roofs
 - a. R.C.C Slab (Yes/No)
 - b. R.S. joints & Battens (Yes/ No)
 - c. Wooden joints & Battens (Yes/No)
10. Material used for Walls
 - a) Mud Mortar (Yes/No)
 - b) Cement Mortar (Yes/ No)
 - c) Plaster Lime Mortal (Yes/No)
Cement Mortal (Yes/No)
11. Flooring
 - a. Conglomerate (Yes/No)
 - b. Terrazo (Yes/ No)
 - c. Brick Paving (Yes/ No)
12. A detailed drawing indicating dimensions of the rooms & location of doors and windows is attached.

Date :-

Signature of Principal with school Stamp




(For the use of the PWD B&R department)

- a) I...Vinod Garg.....S.D.E. along with..Chander Mohan Sirohi.....
have visited this School on...G.R. 12-2021.... and have inspect it from all angles of
Safety and found it fit for normal use as School building
- b) In case any addition, alteration, extension or modification of this building is to be carried
out, it should be carried out under the supervision of technical qualified Engineer and
after its completion this Certificates may again be obtained from the undersigned.
- c) In case the building is affected by flood or if there is settlement to walls foundations
edging or roof, immediate inspection of the undersigned be arranged to check the stability
and safety of the building
- d) The building can be safely occupied for normal use upto..31-03-2022.....
- e) Inspection fee amounting to RS...1,00,000.....has been deposited by the school
vide G.R. No...174/2404..... dt. ...05-10-2021.....

Countersigned

Executive Engineer


Sub Divisional Engineer
Prd. Div. No. 2
Sub Divisional Engineer