

**PROFORMA FOR THE SAFETY OF SCHOOL**  
**BUILDING**  
**PART- 1**

(To be filled by the Head of School/ Institute)

1. Name of the School:- SRI GURU HARGOBIND CONVENT SR. SEC. SCHOOL
2. Location:- NATHANA, 151102, POOHLI ROAD NATHANA
3. Plot Area:- 19 KANAL, 16 MARLA
4. Plinth Area:- 565.77 S.Q. FT
5. Number of Storey's:- 03
6. Year of Construction of Building:- 2013
7. **If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given**
  - a) Name of the Engineer with qualification:- NAVRAJ SINGH GREWAL
  - b) Address of Engineer:- BATHINDA GOLE MARKET S.O. - 19  
2nd FLOOR
  - c) Set of Structural drawings used in the construction, if available:-
  - d) Name & address of Architect with qualification:- NAVRAJ SINGH GREWAL
8. **Whether the building has been constructed for the purpose**
  - a) School : (Yes/No)
  - b) Residential Purpose and converted for use as a School : (Yes/No)
9. **Materials used for roofs**
  - a) R.C.C. Slabs/R.B.C. Slabs : (Yes/No)
  - b) R.S. Joist & Battons : (Yes/No)
  - c) Wooden joists & Battons : (Yes/No)
10. **Materials used for walls**
  - a) Mud Mortar : (Yes/No)
  - b) Cement Mortar : (Yes/No)
  - c) Lime Mortar : (Yes/No)
11. **Flooring**
  - a) Conglomerate : (Yes/No)
  - b) Terrazo : (Yes/No)
  - c) Brick Paving. : (Yes/No)
12. **A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows (Attached)**

Date:-.....



Principal  
Signature with Stamp of the school  
P.O. of the School/Institution  
Affiliation Code No. 1639976

**PART-II**  
(To be filled by the  
S.D.E.)

- a) I have visited the above mentioned school on dated 8/5/24..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (indicate upto which it can be used)  
31-03-2025
- e) Inspection has been completed vide G.R. No. 1742420 D1  
2/5/24.

  
Sub Divisional Engineer,  
Prov. Sub Divisional Engineer,  
P.W.D. (B&R) Br. Bathinda.



